

Linden Hall CAE Photo Album

October 6, 2011

Electrical Service / Masonry Progress /
Attic HVAC

By Chambers & Associates

**Location of new
electrical service
pole**



**View from Main
Street**



**View from over
the Main Street
fence**



**View from the
Parking Lot**



Masonry Staging Area



Looking north



Looking northwest



Looking west



Looking northwest



**Masonry started
adjacent to
Steinman
Performing Arts**



Looking southwest
from the ramp



Looking west from
the ramp



Looking northwest
from the lower
level



**Looking north
west from the
lower level**



Looking northwest
from the lower
level



Looking south
from the lower
level



Looking northeast
from the lower
level



Looking east from
the lower level



Looking east from
the existing
basement landing
level



Looking north
from the existing
basement landing
level over the
elevator shaft



**Looking north at
the foundation
poured around the
rock in the existing
foundation**



**Looking east from
the basement at
the rock in the
foundation
encased in
concrete**



**Looking east at the
north basement
wall of the 1844
addition**



Looking north
from under the
1769 porch



Looking east from
under the 1769
porch



Looking northeast
from under the
1769 porch




**Looking north
from under the
1769 porch at
column footings
ready for steel**




Looking north
from under the
1769 porch at
1804 section




**Attic ductwork
and furnaces**



**Attic ductwork
and furnaces**



**Attic ductwork
and furnaces**



**Attic ductwork
and furnaces**



**Attic ductwork
and furnaces**



**Attic ductwork
and furnaces**



**Attic ductwork
and furnaces**



**Attic ductwork
and furnaces**



**Attic furnaces
being moved
upstairs**



**Job site from the
third floor**

